



Workers attempt to repair damage to a rock headwall on Edisto Beach after the nor'easter storm on February 27, 2005 at Edisto Beach, SC.



This groin on Edisto Beach, S.C. is in process of repair from the recent storm.



This house was undercut by waves during the storm, but it was not condemned.



This house was also undercut by waves, and it was condemned.



Damage caused by recent storm to headwall in foreground and rock rip-rap in background.



Houses undercut by recent storm waves.

Pictures taken by [Will Doar](#), South Carolina Geological Survey.